




You will need to 2 x drill and tap M5 hole so you can mount the X axis DRO on the mill table.
And another 2 x drill and tap M5 hole so you can mount the sensor on below deck, the thin metal and screws included in the DRO package will allow you to align the sensor so it can parallel with the DRO unit.



This is the view of the Y axis installation, to install the round extended shaft, you will need to drill 2 M4 tap hole, so you can screw in the extender, then install the special L shape plate (the plate will have screw hole that allow you to secure to the y Axis DRO sensor). The small pillow block with set screw will allow you to fine adjust the DRO parallel with the Y axis. Then you will need to drill 2x drill and tap M5 hole on the base, so you can secure the y Axis DRO.



The small black aluminum plate allow you to install to the Z axis mill head just by unscrew the machine screw, so the large L aluminum bracket can mount on top



The complete view of the Z axis, secure the Sensor to the large L bracket.